

Technical Bulletin

TB3400-010

Sheet: 1 of 1

Issue: 15.06.2011

3400 Neck Forming System

Upgrade of Rotary Union

CATEGORY: Advised At Next Maintenance

Carnaud Metalbox Engineering have upgraded the Rotary Union on the 3400 Necker as a result of customer feedback and successful field trials. Part number 2394605 B includes an adaptor to ensure compatability with all CmbE 3400 machines.





Discontinued Rotary Union: 770671

Replacement Rotary Union: 2394605 B

Note: The regulated air pressure to the lubrication pumps must be limited to 3 BAR (43 PSI). See CmbE Technical Bulletin TB3400-009.

Repair kits for the new Rotary Union can be purchased from CmbE as follows.

003-12210-BTS-SK: Includes seals only.

003-12210-BTS-LK: Includes seals and also bearings.

For further information regarding this Technical Bulletin please contact either of the contacts below quoting Technical Bulletin Number TB3400-010

Note: a complete Library of Technical Bulletins is accessible on the Company Web Site.

CarnaudMetalbox Engineering Limited,
Dockfield Road, Shipley,
West Yorkshire, BD17 7AY, UK
Tel: +44 1274 846200, Fax: +44 1274 846201
email: sales@CMBEcanmaking.com

CarnaudMetalbox Engineering Limited, 79 Rockland Road, Norwalk, Connecticut 06854, USA Tel: +1 203 853 7325, Fax: +1 203 866 7627

email: sales@CMBEcanmaking.com