

Upgrade of Rotary Union (Issue 2)


TB3400-010

15/06/2011

Category: Advised at next maintenance.

Summary:

CarnaudMetalbox Engineering Ltd (CMbE) have upgraded the Rotary Union on the 3400 Necker as a result of customer feedback and successful field trials. **TB3400-010#01** includes an adaptor to ensure compatibility with all CMbE 3400 Die Neckers.



Discontinued Rotary Union: 770671



Superseded Rotary Union: 2394605B
Replacement Rotary Union: TB3400-010#01

The regulated air pressure to the lubrication pumps must be limited to 3 BAR (43 PSI). This is referenced in TB3400-09.

Repair kits for the new Rotary Union can be purchased from CMbE as follows:

003-12210-BTS-SK: Includes seals only.

003-12210-BTS-LK: Includes seals and bearings.

Note:

For further information regarding this Technical Bulletin, please contact either of the references at CarnaudMetalbox Engineering Ltd below, quoting Technical Bulletin reference **TB3400-10** in addition to the serial number of your machine.

A complete library of Technical Bulletins is now available on the company website.