

Applicable to Hydraulic Clutch and Brake units only

CATEGORY: Recommended immediately

Summary: CarnaudMetalbox Engineering are aware of instances where the manifold connections on the Hydraulic Power Unit of the Hydraulic Clutch and Brake Bodymakers have been incorrectly connected. This Technical Bulletin details the procedure for checking the manifold connections and any subsequent remedial action.



Left Manifold

Right Manifold

NOTE: For further information regarding this Technical Bulletin please contact either of the contacts below quoting Technical Bulletin number **TB5000-073** and your machine Serial Number. A complete library of technical bulletins is available on the company web site.

CarnaudMetalbox Engineering Ltd,
Dockfield Road, Shipley,
West Yorkshire, BD17 7AY, UK
Tel: +44 1274 846200, Fax: +44 1274 846201
e-mail: sales@CMBEcanmaking.com

CarnaudMetalbox Engineering Ltd,
79 Rockland Road, Norwalk,
Connecticut 06854, USA
Tel: +1 203 853 7325, Fax: +1 203 866 7627
e-mail: sales@CMBEcanmaking.com