



CATEGORY: Recommended on all Bodymakers featuring Microdomer upgrading to special studs

Summary: CarnaudMetalbox Engineering Ltd recommends the removal of 2 off M12 x 90 socket head screws, from the Dome Station assembly as they are NOT required during production ONCE the 8 off special studs have been fitted to the Dome Station. The M12 x 90 soc hd screws are an optional feature to retain the Microdomer in the Dome Door while removing the special studs.

This improvement ensures that operational efficiency should the M12 screws fail across any affected 5000 Bodymakers.



NOTE: For further information regarding this Technical Bulletin please contact either of the contacts below quoting Technical Bulletin number **TB5000-075** and your machine Serial Number. A complete library of technical bulletins is available on the company web site.

CarnaudMetalbox Engineering Ltd,
Dockfield Road, Shipley,
West Yorkshire, BD17 7AY, UK
Tel: +44 1274 846200, Fax: +44 1274 846201
e-mail: sales@CMBEcanmaking.com

CarnaudMetalbox Engineering Ltd,
79 Rockland Road, Norwalk,
Connecticut 06854, USA
Tel: +1 203 853 7325, Fax: +1 203 866 7627
e-mail: sales@CMBEcanmaking.com