



ENGINEERING

Technical Bulletin

TB5000-065

5000 Bodymaker

Issue: 27.02.2014

Dual Air Strip Valve

CATEGORY: Information for Factory Implementation

Summary: New Dual Air Strip Valve Assembly.

CarnaudMetalbox now have available a design up-grade for their Air Strip Valve arrangement offering customers the following benefits:-

The Air Strip Valves can operate alternately or on their own, therefore allowing failed valves to be changed without stopping production.

Doubling the amount of valves halves the duty cycle of each valve, therefore allowing a longer planned maintenance period.

Fitted as standard on all new Bodymakers (from serial number 831s) this Dual Air Strip Valve Arrangement is also available as an upgrade kit for earlier machines.


Retrofit Details:-



Trained operators ONLY to perform this operation

The Dual Air-Strip valve fits directly in place of the existing Air -Strip valve of your 5000Mk2 Bodymaker. Refer to the illustration for the relevant connections.

Note: Electrical considerations will be advised by CarnaudMetalbox on a machine by machine basis.



New Dual Air Strip Valve Assembly

For further information regarding this Technical Bulletin please contact either of the contacts below quoting Technical Bulletin Number [TB5000-065](#) and your machine Serial Number.

Note: a complete Library of Technical Bulletins is accessible on the Company Web Site.

CarnaudMetalbox Engineering Limited,
 Dockfield Road, Shipley,
 West Yorkshire, BD17 7AY, UK
 Tel: +44 1274 846200, Fax: +44 1274 846201
 email: sales@CMBEcanmaking.com

CarnaudMetalbox Engineering Limited,
 79 Rockland Road, Norwalk,
 Connecticut 06854, USA
 Tel: +1 203 853 7325, Fax: +1 203 866 7627
 email: sales@CMBEcanmaking.com