

Improved Rotary Cup Feed

CATEGORY: Recommended

Summary: CarnaudMetalbox Engineering have with the aid of a high speed video camera developed an improved version of the Rotary Cup Feed Arrangement.

This new design has been tested at speeds up to 700cpm without cup damage.

Production trials at 400cpm showed that incidences of cup misfeed were halved compared to machines fitted with the earlier Rotary Cup Feed.


This up-grade gives a smoother peel off from the cup stack with superior guidance from both the Cam and Guides with more accurate loading and positioning of the cup in the Cup Locator.

The new Rotary Cup Feed design can be fitted to all 5000 Bodymaker machines within 12 hours. Minor Guard modifications may be necessary.

For further details about the Improved Rotary Cup Feed please contact either of the contacts below quoting Technical Bulletin Number

TB5000-029

Note: A complete Library of Technical Bulletins is accessible on the Company Web Site.



CarnaudMetalbox Engineering Plc,
 Dockfield Road, Shipley,
 West Yorkshire, BD17 7AY, UK
 Tel: +44 1274 846200, Fax: +44 1274 846201
 email: sales@CMBEcanmaking.com

CarnaudMetalbox Engineering Plc,
 79 Rockland Road, Norwalk,
 Connecticut 06854, USA
 Tel: +1 203 853 7325, Fax: +1 203 866 7627
 email: sales@CMBEcanmaking.com