

CATEGORY: Recommended at next maintenance

Summary: CarnaudMetalbox Engineering Ltd introduces a catch assembly for the slideway guard on the 5000 Bodymaker. The catch assembly locks the slideway guard lid in position when opened, thus preventing inadvertent closure of the slideway guard lid and acts as a safety device should the gas struts malfunction. The catch assembly can be retrofitted by attaching the assembly to the slideway guard lid and skirt.

This improvement ensures that operator safety is maintained and eliminates the risk of potential injury.




Figure 1



Figure 2

NOTE: For further information regarding this Technical Bulletin please contact either of the contacts below quoting Technical Bulletin number **TB5000-074** and your machine Serial Number. A complete library of technical bulletins is available on the company web site.

CarnaudMetalbox Engineering Ltd,
Dockfield Road, Shipley,
West Yorkshire, BD17 7AY, UK
Tel: +44 1274 846200, Fax: +44 1274 846201
e-mail: sales@CMBEcanmaking.com

CarnaudMetalbox Engineering Ltd,
79 Rockland Road, Norwalk,
Connecticut 06854, USA
Tel: +1 203 853 7325, Fax: +1 203 866 7627
e-mail: sales@CMBEcanmaking.com